

Sliptest Australia Pty Ltd NATA Accreditation No: 15374 11 Fuchsia Way Gaven QLD 4211., Gaven, QLD, 4211 kathryn@sliptest.com.au www.sliptest.com.au 1300 754 783

# Artistic Flooring - VANCOUVER CARPET TILE 500x500 BLUE

## 05 Feb 2018

## Slip Resistance Classification of New Pedestrian Surfaces - AS4586:2013 Appendix A

Date Tested:	05 Feb 2018					
Test Report Number:	KO050218-5					
Client Name & Address:	Artistic Flooring - 6/98 Ingleston Road WAKERLEY QLD 4154					
Test Site / Project :	Artistic Floor Depot					
Product / Sample Tested :	MUNICH CARPET TILE 500×500 BLUE FLECK					
Wet Pendulum Test carried out using :	Slider 96 (4S) Rubber slider					
Record ambient temperature (°C)	29					
Testing Officer :	Kathryn Ording - Munro-Stanley Portable Skid Tester #1133 - 30.08.17					
	<i>~~</i>					

**Testing Officer Signature** 

# P

### **Test Results :**

No. of Samples	Sample No.	Swing 1	Swing 2	Swing 3	Swing 4	Swing 5	Mean BPN of last 3 swings :	Surface Picture
1 Sample	Area 1	79	80	80	82	82	81	
	Area 2	80	81	81	82	82	82	
	Area 3	82	84	85	85	85	85	
	Area 4	81	82	83	84	84	84	
	Area 5	81	83	83	84	84	84	

## Mean BPN Slip Resistance Value (SRV)

CLASSIFICATION using Slider 96 (4S Slider)

P5 = > 54

Accedited for Compliance with ISO/IEC 17025. The information presented herein and on the Sliptest Report is copyright and is protected by copyright law, any reproduction of this information and test report except in full is prohibited. Sliptest Australia Pty. Ltd. performed this on site test with reference to the following Australian Standard testing criteria, of AS 4586:2013 Classification of new pedestrian surface materials. Appendix A – Wet Pendulum Test Method and Hand Book HB 198: 2014 with reference to AS/NZS 4663: 2004 Slip Resistance measurement of existing pedestrian surfaces and HB 197: 1999. These results to not account for Future Wear, Maintenance or Contamination of this surface once in-situ.

#### CONFIDENTIAL

Page 1

83